The Thomas Pumphrey House is an example of a mid-19th century, Greek Revival Style, center-hall plan dwelling. Both its stylistic embellishment and floor plan representative its period of construction. This type of dwelling is a common on both a local and national level.

The house was built by Thomas Pumphrey (1824-1894), a member of a large and prosperous family who settled in north Anne Arundel County in the second half of the 18th century. Pumphrey was a very successful truck farmer and this house represents the architectural predilection of a wealthy, mid-to-late 19th century Anne Arundel County farmer.

AA-77 Thomas Pumphrey House

MARYLAND COMPREHENSIVE STATE HISTORIC PRESERVATION PLAN DATA

Geographic Organization: Western Shore

Chronological/Development Period(s): Agricultural-Industrial Transition (1815-1870)

Prehistoric/Historic Period Theme(s): Architecture

Resource Type:

Category Type: Building Historic Environment: Rural

Historic Function(s) and Use(s): Dwelling

Known Design Source: None

Maryland Historical Trust State Historic Sites Inventory Form

Survey No. AA-77

Magi No.

DOE ___yes ___no

<u>1.</u>	Name	(indicate preferred name)			
histo	ric	Thomas Pumphrey House			
and/	or common				
2.	Location	on	· · · · · · · · · · · · · · · · · · ·		
		<u> </u>			
stree	t & number	619 Furnace Branch Road		not fo	or publication
city,	town	Glen Burnie	vicinity of	congressional district	
state		Maryland	county	Anne Arundel	
3.	Classif	ication			
X	gory district building(s) structure site object	Ownershippublicprivateboth Public Acquisitionin processbeing considerednot applicable	Status occupied x unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Useagriculturecommercialeducationalentertainmentgovernmentindustrialmilitary	museum park private residence religious scientific transportation x other: abandoned
4.	Owner	of Property	(give names and mailing ad	dresses of <u>all</u> owners)	
name		Burwood Road Associated L	imitied Partnership		
stree	t & number	7954 Baltimore-Annapolis B	•	telephone no.:	
city,	town	Glen Burnie	state and zip code:	Maryland 21060	
<u>5.,</u>		on of Legal Des		Maryland 21000	
court	house, registry	y of deeds, etc. Anne Arui	ndel County Court House	liber 4	
street & number		Church Circle		folio 351	
city,		Annapolis	4. 11.4	state MD	
<u>6.</u>	Repres	entation in Exis	ting Historical	Surveys	
title					
date			federal	state count	y local
ُبين	sitory for surve	ey records			
city,	town			state	

7. Description			Survey No. AA-77		
Conditionexcellentgoodfair	deterioratedx ruinsunexposed	Check one x unaltered altered	Check one x original site moved date of move		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Thomas Pumphrey House, built in 1863, is in an advanced state of deterioration. It has been subject to fire and vandalism, and is presently unsecured.

The two-and-a-half story, five-bay, south-facing dwelling is constructed of brick laid in 5:1 American Bond. The center passage, single-pile plan front block is augmented by a three bay rear ell that projects from the north side. This arrangement gives the building an L-shaped plan. Originally, the slate-covered gable roof was pierced by two corbelled, interior end chimneys, and four (two in each side of the roof) gable-roofed dormers with partial returns. Portions of one chimney have fallen and a front dormer is now missing. A corbelled brick cornice embellishes the otherwise plain roofline.

The badly damaged windows are six-over-six, double-hung sash types with jack arches above and wood sills below each opening. The centrally placed front entrance had a multi-paned transom and sidelights. These are missing, but a paneled casing and molded crown, remain intact.

Three other entrances are present. A rear entry, in direct line with the previously described opening, is removed of both its door and casing. The two remaining doorways are in the ell and are positioned in direct alignment with each other. That in the east wall has lost its door, but the casing, much simpler than that in front, remains. A badly deteriorated paneled doors survives in the ell's west wall. All doorways are topped by a jack arch, identical to those over the windows.

building's interior is extensively damaged. Prominent architectural elements, including mantles, w....ow surrounds, balustrade and newel post have been removed.* Plaster has fallen exposing the brick. Surviving elements of the open string staircase include open stringer brackets with vertical panels below. A steep, narrow winder staircase is located in the rear of the house. This is badly charred balustrade and rail is missing.

Local historian Ora Pumphrey Smith provided Anne Arundel County's, Department of Planning and Code Enforcement with several historic photographs. These photographs depict the building's exterior condition in the early 20th century and will be useful references in any future restoration projects.

* Concern over the building's decay prompted Dr. Stephen Hittle to remove and store these elements. Dr. Hittle lives at the Robinson House (AA-130), 343 Baltimore Annapolis Boulevard; Severna Park, Maryland 21146.

8. Signif	ficance		Survey N	lo. AA-77
Period	archeology-prehistoric archeology-historic agriculture x architecture art		landscape architecture law literature military music philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	1863	Builder/Architect		
Applic	·	ABx CD ABCD national x state x local	EFG	
Level	of Significance:	national <u>x</u> state <u>x</u> local		

Prepare both a summary paragraph of significance and a general statement of history and support.

The Thomas Pumphrey House was constructed in 1863 and represents the architectural predilection of a wealthy Anne Arundel County truck farmer. Its vernacular Greek Revival styling is typical of the period, and its large size and brick construction are evidence of Thomas Pumphrey's affluence.

Thomas Pumphrey (1824 - 1894) was a member of a large and prosperous family who settled in north Anne Arundel County in the second half of the eighteenth century. Thomas lived on a truck farm adjacent to those of his younger brothers Charles (AA-1073) and Nathan, of whom controlled hundreds of acres. According to the agricultural census, Thomas owned approximately 600 acres, 300 of which were improved. His farm was valued at \$29,000, which is the third highest assessment in the 5th election district of Anne Arundel County in that year (1).

By the middle of the nineteenth century agricultural production in north county had shifted from tobacco, grain, and cereals crops, to truck farming. This form of agriculture focused on growing fresh fruits and vegetables, e.g. strawberries, cantaloupes, stringbeans, etc. for shipment to regional market centers. North Anne Arundel County was favored with sandy soil and an established railroad system, a combination of conditions especially suited to truck farming.

Thomas Pumphrey's success is manifested in the elegant Greek Revival house that he built in 1863 (2). This building, which replaced a frame dwelling that burned, is reflective of the architectural taste of the period, and represents the living style of one of north Anne Arundel County's most successful farmers in the third quarter of the nineteenth century.

9. Major Bibliographical References

Survey No. AA-77

(1) Agricultural Census of the United States, District 5; 1850, 1860, 1870.

(2) Anne Arundel County History Notes, Vol. XVIII No 2. Anne Arundel County Historical Society, January 1987.

10. Geogra	aphical Data					
	d property435 acres Relay	- Quadrangle	scale 1:24,000			
UTM References	Do NOT complete UTM references	B				
Zone Easting	Northing	Zone Easting	Northing			
c		D				
E		F				
G		H				
Verbal boundary description and justification .435 acres is the lot associated with the Thomas Pumphrey House						
List all states and c	ounties for properties overlapping sta	te or county boundaries				
<u>;</u>	code	county	code			
state	code	county	code			
11. Form Prepared by						
name/title	Sherri Marsh					
organization	Anne Arundel County Historic Sites Sur	vey date 8/22/9	6			
street & number	2664 Riva Road	telephone (4	110) 222-7441			
city or town	Annapolis	state	Maryland			

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust


DHCP/DHCD

100 Community Place

Crownsville, MD 21032-2023

410-514-7600







Anne Arundel co, mary land

Donna M. Wave, Photographer;

NEG. AT MD SHPD

South Elevation

Thoto I of 5



AA-MM Thomas Pumphrey House Anne Arundel W., Maryland Donna M. Ware, Photographor Octobor 1986 Negative at Maryland SHPO EAST ELEVATION Photo 2 of 5



AA. TT Toxing - Punphicy House Anne Arundel Co., MARYLAND Donna M. Ware, Photographer October 1986 negetire at Mary LAND 571 PO NE Perspection Photo 3 of 5



AA-TT Trummes Kumphiter House Anne Arundel Co., MARILAND Donna M. Ware, Photographer Oxfolder 1986 Negative at MARILAND SIPO Nr Frederick



AA- nn Thomas Pumphrey Hruse ANNE ARUNDEL (O., MARILAN) DONNA M WARE, Photographer Deadive at MARILAND SHPO MEEL LLEVATION 1hot 5 6-5